

Basement Flood Clean-up in West Malling, Kent

CASE STUDY

TABLE OF CONTENTS

THE BRIEF	2
THE OBJECTIVE	2
THE TECHNICAL PART	3



West Malling, United Kingdom





Copyright © IRG Limited. Registered in England & Wales: No. 10822482. All rights reserved.



Basement Flood Clean-up in West Malling, Kent

CASE STUDY

THE BRIEF

Following a leak from a mains water pipe, three properties in West Malling, Kent, suffered from water ingress into their basements. We were called to site to scope and carry out required remedial work to minimise secondary damage. If a property is not dried out adequately, it can lead to mould growth and rot which can then lead to extensive and expensive repairs.

The basements of No. 15 and No. 19 have been turned into living areas, and No. 17's basement was still being used as a storage area. All three basements were affected.

THE OBJECTIVE

The properties were built in the late 1800s and are privately owned. Built primarily of brick, the Kent terrace houses boast a pitched timber frame roof, completed with tiles. The properties all have rear gardens, although they do not have any front garden – the front door opens onto the public footpath and it is from the front where the water penetrated the basements.







0808 2394 082

https://www.idealresponse.co.uk



copyright © IRG Limited. Registered in England & Wales: No. 10822482. All rights reserved.



Basement Flood Clean-up in West Malling, Kent


CASE STUDY

THE TECHNICAL PART

No. 15:

The basement of No. 15 has been converted into a kitchen. The floor has a concrete base with ceramic tiles throughout which required complete and thorough sanitation. A section of the dry lined wall also required removing where mould had begun to grow.

Within the basement area, one of the walls had a WME reading of 21.2 and water tracked up to about 300mm. Wood Moisture Equivalent (WME) is the theoretical %mc (moisture content) value that would be attained by a piece of wood in contact with and in moisture equilibrium with the material under test. The higher the reading, the damper the material is, with 100% WME being the maximum value. As a general rule of thumb, a WME reading should be less than 17.5% WME.



Drying equipment needed to be installed to ensure an adequate dry out of the basement. One dehumidifier, along with one air mover to increase airflow was specified for this property.

No. 17:

No. 17's basement was the only one of the three that was still being used as a storage area. Again, it consisted of a concrete floor and required full and thorough sanitation, as well as drying. One dehumidifier alongside one air mover was installed to dry out the area.

No. 19:

The second of the two basements which were converted to living areas, No. 19 required lower sections of plasterboard removing due to the water penetration. Plasterboard can bow, peel, stain, and encourage significant mould growth should it suffer from water damage.

0808 2394 082

https://www.idealresponse.co.uk





Basement Flood Clean-up in West Malling, Kent

CASE STUDY

As with the others, the whole basement area required thorough sanitation and a drying regime consisting of one dehumidifier and one air mover.

Wanting to see more case studies? Click here to view more of our case studies!

Ideal Response Disaster Recovery & Hygiene Experts

Phone:0808 2394 082Email:info@idealresponse.co.ukWebsite:www.idealresponse.co.uk

0808 2394 082

https://www.idealresponse.co.uk

